Serial Application No. 09/245,596

Page 5, line 10, change "top surface" to --cutting surface--.

Line 5, line 11, change "top surface" to --cutting surface--.

Page 5, line 15, change "top surface" to --cutting surface--.

Page 5, line 30, change "top surface" to --cutting surface--.

Page 7, line 22, change "the top surface" to --a cutting surface--.

Page 7, line 34, change "top surface" to --cutting surface--.

Page 8, line 1, change "top surface" to --cutting surface--.

Page 9, before line 23 insert - Fig. 5D shows a cross-sectional fragmentary side view of a pocket portion of the cutting blade shown in FIG. 5A.

Page 10, line 9, change "having a top surface" to --having a substantially flat cutting surface--.

Page 10, line 10, change "top surface" to --substantially flat cutting surface--.

Page 10, line 14, change "top surface" to --cutting surface--.

Page 10, line 16, change "top surface" to --cutting surface--.

Page 10, line 20, change "top surface" to --cutting surface--.

Page 10, line 21, change "top surface" to --cutting surface--.

Page 11, line 24, change "top surface" to --cutting surface--.

11

12

13

 \bigcirc

(

Serial Application No. 09/245,596

Page 11, line 29, change "top surface" to --cutting surface--.

Page 11, line 36, change "top surface" to --cutting surface--.

Page 11, line 37, change "top surface" to --cutting surface--.

Page 12, line 1, change "top surface" to --cutting surface--.

Page 12, line 2, change "top surface" to --cutting surface--.

Page 12, line 7, change "top surface" to --cutting surface--.

Page 12, line 9, change "top surface" to --cutting surface--.

Page 12, line 14, change "top surface" to --cutting surface--.

Page 12, line 30, change "top surface" to --cutting surface--.

Page 12, line 31, change "top surface" to --cutting surface--.

Page 13, line 6, change "top surface" to --cutting surface--.

Page 13, line 13, change "top surface" to --cutting surface--.

Page 13, line 15, change "top surface" to --cutting surface--.

Page 13, line 29, change "38" to read --30--.

Page 15, line 6, change "Pocketed portion 96" to --Referring to Fig. 5D, pocketed portion 96--.

Page 15, line 11, after "angle" insert --designated A_1 --.

3

Ó

94

Serial Application No. 09/245,596

Page 15, line 15, after "angle" insert --designated A_2 ---.

Page 15, line 16, change "acute angle 102" to --acute angle designated $A_1--\ .$

Page 17, line 30; change "top surface" to --cutting surface--.

Page 17, lines 33-34, change "top surface" to --cutting surface--.

Page 18, line 3, change "top surface" to --cutting surface--.

Page 18, line 12, change "top surface" to --cutting surface--.

Page 18, line 21, change "top surface" to --cutting surface--.

Page 18, line 36, change "top surface" to --cutting surface--.

Page 19, line 3, change "top surface" to --cutting surface--.

Page 19, line 14, change "top surface" to --cutting surface--.

Page 19, line 21, change "top surface" to --cutting surface--.

Page 19, line 26, after "rotating" insert - in the movement direction of the cutting blade 32--.

Page 20, line 28, change first face 90" to --first face 92--.

Page 21, line 28, change "top surface" to --cutting surface--.

4

Q

25